

EXHIBIT 1
Violations of NPDES Construction Stormwater Permits

Dominion Site	Permit Number	Violation Description
Bremo Pond Closure	VAR-10H875	VADEQ inspection report dated 4/4/16 identifies deficiencies with the operation and/or maintenance of BMPs.
Louisa Solar	VAR-10I424	VADEQ inspection reports dated 9/27/16 and 10/6/16 identify deficiencies with the operation and/or maintenance of BMPs.
Liberty Station	VAR-108818	EPA report dated 6/14/16 identifies deficiencies with the operation and/or maintenance of BMPs and with the corrective action implementation.
Scott Solar	VAR-10I027	VADEQ inspection reports dated 8/11/16 and 9/29/16 and 12/12/16 identify deficiencies with the operation and/or maintenance of BMPs and with the SWPP.
Brunswick Power Station	VAR100578	Dominion self-inspection reports pertaining to “Location A” identify deficiencies with the operation and/or maintenance of BMPs and with the corrective action implementation from 1/6/14-5/12/15.
Brunswick Power Station	VAR100578	Dominion self-inspection reports pertaining to “Location B” identify deficiencies with the operation and/or maintenance of BMPs and with the corrective action implementation from 1/6/14-12/29/14.
Brunswick Power Station	VAR100578	Dominion self-inspection reports pertaining to “Location C” identify deficiencies with the operation and/or maintenance of BMPs and with the corrective action implementation from 8/29/14-4/10/15.
Hollymead	VAR-100076	From July through September of 2014, inspection reports show multiple Corrective Actions that are not timely implemented, BMP compliance concerns and that the site is not in compliance with the SWPPP.